

**DATE:** April 9, 2014

**TO:** Gayle Nurre, Principal

**SUBJECT:** Flower Mound ES - IAQ - Initial Contact - Room 143

Yesterday 4/8, I received W.O. #183035: "There is a corner of what looks like wall paper or paint that is peeled up in Room #143. I don't know if it is dirt or something else like mold underneath it. It is right under the window." This morning 4/9, Keith Templin and I looked at the area in Room 143. Our conclusion is to seal the vinyl area, and this summer, cut the sheet rock and replace. Discussed that plan with Tina Joeris. If you have any questions, please contact me.

Thanks,  
Paul

Paul Siddall  
Maintenance Energy Auditor (IAQ)  
Facility Services  
Lewisville ISD  
469-446-8882