

DATE: January 24, 2014

TO: Michael Thakur, Assistant Principal

SUBJECT: Shadow Ridge MS - IAQ - Initial Contact - West outside wall near Room 1021

This morning 1/24, I received W.O. #175871: "Teacher concern about possibility of mold on the outside wall of room 1021." This morning 1/24 8:15 AM, I inspected the area with you. As I told you, I will be sending this to the West Zone Facility Services, and they can make arrangements to Power Wash the outside wall. The West Zone will keep you informed on the day and time this will be completed. If you have any questions, please contact me.

Thanks,
Paul

Paul Siddall
Maintenance Energy Auditor (IAQ)
Facility Services
Lewisville ISD
469-446-8882

DATE: February 3, 2014

TO: Mike Thakur, Assistant Principal

SUBJECT: Shadow Ridge MS - IAQ - Results & Final report - West side of Building-
Outside brick

As of this morning 2/3, the outside brick of the West wall by Room 1021, has been Power Washed. There is still brown dirt on the wall, in the corner, that is splashed up from this last weekend's rain. If you have any questions, please contact me.

Thanks,
Paul

Paul Siddall
Maintenance Energy Auditor (IAQ)
Facility Services
Lewisville ISD
469-446-8882