

COMMITTED TO EXCELLENCE

DATE: March 27, 2008

TO: Sherry Wagner, Principal

SUBJECT: Highland Village ES - IAQ - Air Test in Hallway between Rooms 602 & 604

On Thursday 3/7, I received Work Order #89115: "IAQ-Please check 600 Hall between 602 & 604. Roof leak was found to be dripping down in the wall". Since that time, the roof has been repaired. I visited the area yesterday 3/26, and there doesn't seem to be anything that is visible. But I am going to have EFI do an Air Test in that hallway to be sure we don't have other issues. We should have the results back by Tuesday 4/1. If you have any questions, please call me.

Thanks,
Paul

Paul Siddall
Special Projects (IAQ)
Facility Services
469-446-8882