

COMMITTED TO EXCELLENCE

**DATE:** December 13, 2012

**TO:** Chad Russell, Assistant Principal

**SUBJECT:** Flower Mound HS - IAQ - Air Test - English Work Room

On Monday, 12/10 you sent me this concern from Sandy Mattox: *"Since I brought the carpet in the English workroom to your attention, I feel I must fully inform you about the situation. There was a leak in that workroom (carpet in front of restrooms was wet due to it) for probably at least a year off and on because the district had difficulty finding the source of the leak and getting it fixed (This was while Mr. Moon was principal and while Mr. Moreno was in charge of the building, not Chad). At some point, I told Adrian the district needed to test for mold due to the source (boy's restroom, I believe) and duration of the leak, as it had tested for mold in Angie's room due to a leak, which resulted in sheet rock and flooring being replaced in her room. Instead, after the source of the leak was finally identified and fixed, someone from maintenance came out and said he did not see or smell any mold. Since it appears something is growing in the carpet, it may also be growing in the sheet rock, so I still think indoor air quality should test the English workroom for mold in case some of the sheet rock as well as carpet needs to be replaced. I tried in the past on this issue and gave up, but your interest in fixing- up the building (and I applaud your efforts) has encouraged me to try again. Let me know if you have any questions."*

I set up Work Order #141208, and inspected the room on Wednesday 12/12. I have requested a P.O. to have the English Work Room Air Tested. Southwest GeoScience will be doing the Air Test at the end of this week. We should have the results back by Wednesday 12/19.

If you have any questions, please call me.

Thanks,  
Paul

Paul Siddall  
Special Projects Manager (IAQ)  
Facility Services  
Lewisville ISD  
469-446-8882